



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
YELAHANKA		3		Atturu			
Street ID		Street Name		Significant Landmark			
W0374, W0697, W0366, W0370, W0372, W0703, W0705, W		1st Main Rd, NA, S Krishnappa Lyt		4th main and 5th cross roads in Attur			
Segment No.		Total Length (m)					
3/C-W0374/S111555		400.51					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	151.93	77.567746	13.102105	77.569133	13.101910	W0695	W0707
2	248.58	77.567876	13.099803	77.568041	13.102044	W0374	W0366

Work Details			
History of Road / Lane / Circles			
Name of the Work		Sanctioned Estimated Amount (Rs.)	
Construction of lead of drains 4th main and 5th cross roads in Attur ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone		1999000	
		Sanctioned Year	
		2014	
Year		Type of Work	
2014 - 2015		Others	
Tender		Other Work Type	
		Construction of lead of drains	
Tender		Work Details	
		Construction of lead of drains 4th main and 5th cross roads in Attur ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	
		Job No. / Work Code	
		003-15-000011	
Work Order No.		Work Order Date	
EE (YNK.D) E-PMT-4/WO/88/2014-15		18/02/2015	
		Period of Extension	
		90 DAYS	
Defect Liability Period From		Defect Liability Period To	
30/06/2015		29/06/2016	
		Multiple road involved with the same Job No/ Work Code #	
		Yes	

Contractor Details		
Name of Contractor		Contractor Reg No (BBMP/PWD)
Y A DHANASHEKAR		
Phone No.		E-Mail ID
		Expenditure Booked \ Released (Rs)
		0.00
Zone: YELAHANKA Ward No: 3 Ward Name: Atturu		

Street ID: W0374,
W0697,
W0366,
W0370,
W0703, W0705

Field Inspection Details

Number of Trees

Any Other Information

Name

12

PRADEEP

Date of Inspection

Remarks

12/06/2017

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 3

Ward Name: Atturu

Street ID: W0374,
W0697,
W0366,
W0370,
W0370, 1st

Drain Condition



This photo seems out of range

Drain Condition



This photo seems out of range.

Drain Condition



This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	12/06/2017	12/07/2017	COMPLETED
SE	VASU K M	12/06/2017	12/07/2017	COMPLETED
EE	SRINIVAS REDDY	12/06/2017	12/07/2017	COMPLETED
AEE	ASHOK	12/06/2017	12/07/2017	COMPLETED
AE	PRADEEP	12/06/2017	12/07/2017	COMPLETED
AE	PRADEEP	12/06/2017	12/07/2017	COMPLETED

ACB

Zone: YELAHANKA

Ward No: 3

Ward Name: Atturu

Street ID: W0374,
W0697,
W0366,
W0370,
12/07/2017 12:00